

ACLARACION DE www.radarmalvinas.com.ar

El siguiente documento se encuentra en el sitio

<http://www.nationalarchives.gov.uk>

en donde usted puede leerlo directamente en su formato original y acceder al resto del sitio.

Copyright © 2012 National Archives UK

Se refiere a:

13MAY82 0206Z – HMS Glasgow a CTG 317.8. Ataque a Glasgow SITREP 5.

(PREM 19/647) (desclasificado DIC 2012)

A efectos de preservarlo como documento histórico para el caso en que el archivo original o el sitio que lo contiene no figurasen más en internet, a continuación se ha realizado una copia.



CJS
C
H
B
DS 11

S E C R E T

CXK093 13 0531 1300733

FOR CXK

IMMEDIATE/IMMEDIATE 130206Z MAY 6

FROM HMS GLASGOW
TO CTG 317.8
RADM NAVAL
CTF 317
HQ IMVICIBLE
INFO HMS BRILLIANT

S E C R E T

SIC 13F/15D

DAMAGE SITREP 5.

1. AER SHOPPING NOW MORE SUBSTANTIAL BUT PORTSIDE NEEDS CONSOLIDATION TO REDUCE WATER FLOW
2. HAVE STARTED RESTORING WATERTIGHT INTEGRITY GENE-EMP BULKHEAD
3. SLOWLY LOSING HP AIR SYSTEM PRESSURE ONE COMPRESSOR ONLY AVAILABLE ATTEMPTING TO IDENTIFY AND ISOLATE LEAKS
4. ALL PROPULSION SYSTEM ELECTRICAL AUXILIARIES UNSEFUICABLE FOLLOWING IMMERSION.
5. REQUEST ROVER GAS TURBINE PUMP, 7X12 IN X2 IN AND 5X41X4111 TIMER AND 1 SHEET THREE QUARTER INCH PLY
6. PROPULSION SYSTEMS GENERATORS AND HP AIR ALL OF LOW INTEGRITY MORE PERMANANT REPAIR OF HOLES IN SHIPS SIDE REQUIRES CALM WATER

PAGE 2 RBDPSKD 733 S E C R E T

IN MEANTIME SPEED RESTRICTED TO 14 KNOTS MAXIMUM BUT WOULD PREFER 10 KNOTS RAS ASTERN POSSIBLE BUT NOT AFFAM ALTHOUGH WEAPON SYSTEM SERVICEABLE REGRET GLASGOW IS UNABLE TO MEET PRESENT OPERATION COMMITMENT

BT

DISTRIBUTION IEF

CXN	1	DSC(NAVY OPS)	ACTION	(CXU	1	DNOT(DD)
CUP	1	ACNS(O)				
CSO	3	BATH SUPP GROUP				
CAF	4	CGRN				
CMS	1	CHS				
CXK	2	COSEEC				
CAG	2	DOHPS				
CYC	1	DIC				
CNH	1	DCNS				
CHG	1	DS 5				

S E C R E T